

Docket No. SA-537

Exhibit No. 6-B

NATIONAL TRANSPORTATION SAFETY BOARD

Washington, D.C.

Attachment 1 – Photographs

(52 Pages)




Photo 1. Overhead view of SFO runways 28L and 28R.



Photo 2. Left side of airplane from the 11 o'clock position.



Photo 3. Left side of airplane from the 9 o'clock position.



Photo 4. Aft of airplane from the 6 o'clock position.



Photo 5. Right side of airplane from the 3 o'clock position.



Photo 6. Door 1L slide/raft.



Photo 7. Door 2L slide/raft.



Photo 8. Door 3L slide/raft.



Photo 9. Door 4L.



Photo 10. Door 1R slide/raft.



Photo 11. Door 2R.



Photo 12. Door 3R.



Photo 13. Door 3R slide/raft.



Photo 14. Door 4R.



Photo 15. Snozzle penetration hole aft of door 2L.




Photo 16. Damage to overhead bin support rail aft of door 2L.



Photo 17. Damage to overhead bin support rail aft of door 2L.




Photo 18. Snozzle penetration hole aft of door 2R.



Photo 19. Interior view of Snozzle penetration hole in 2R lavatory.



Photo 20. View of airplane debris from near the seawall.



Photo 21. 4L jumpseat and aft galley structure.



Photo 22. Door 4L slide/raft bustle and galley floor section.



Photo 23. Debris near beginning of displaced threshold.



Photo 24. Debris on runway 28L.



Photo 25. Cockpit.



Photo 26. Cockpit.



Photo 27. Captain's seat.



Photo 28. First officer's seat.



Photo 29. Left observer's seat.



Photo 30. Right observer's seat.



Photo 31. Door 1L.



Photo 32. Door 1R.



Photo 33. Galley forward of door 1R and 1R slide/raft.



Photo 34. Door 2L



Photo 35. Door 2R.



Photo 36. Door 2R slide/raft.



Photo 37. Door 3L.



Photo 38. Door 3L slide/raft.



Photo 39. Door 3R.



Photo 40. Door 3R slide/raft.



Photo 41. Door 4L.



Photo 42 Door 4L.



Photo 43. Forward-facing view of jumpseat M4A and 4L slide/raft.



Photo 44. Door 4R.



Photo 45. Door 4R slide/raft.



Photo 46. Door 4R slide/raft girt bar and torn girt.



Photo 47. Aft-facing F/A jumpseat L1A.



Photo 48. Forward-facing F/A jumpseat L1B.



Photo 49. Forward-facing F/A jumpseat R1.



Photo 50. Deformation to seatpan of F/A jumpseat R1.



Photo 51. Aft-facing F/A jumpseat L2A.



Photo 52. Aft-facing F/A jumpseat L2A.



Photo 53. Forward-facing F/A jumpseat L2B.



Photo 54. Aft-facing F/A jumpseat R2A.



Photo 55. Forward-Facing jumpseat R2B.



Photo 56. Aft-facing F/A jumpseat L3.



Photo 57. Aft-facing F/A jumpseat R3.



Photo 58. Aft-facing F/A jumpseat R3.



Photo 59. Forward-facing F/A jumpseat L4.



Photo 60. Forward-facing F/A jumpseat R4.



Photo 61. Aft-facing F/A jumpseat M4A.



Photo 62 Aft-facing F/A jumpseat M4B.



Photo 63. Door 1L forward lavatory (closest to the cockpit).



Photo 64. Door 1L forward lavatory (adjacent to door 1L).



Photo 65. Lavatory aft of door 2R



Photo 66. Left lavatory near door 3L, behind row 28 AB.



Photo 67. Center lavatory near door 3L.



Photo 68. Lavatory forward of door 3R.



Photo 69. Lavatory forward of door 4R.



Photo 70. Right center lavatory near door 4R.



Photo 71. Forward galley at door 1R.



Photo 72. Aft mid-cabin galley.



Photo 73. Forward mid-cabin galley (with location of missing galley bin)



Photo 74. Location of missing galley bin in forward mid-cabin galley.



Photo 75. Aft galley.



Photo 76. Hatch door entry to crew rest.



Photo 79. Forward-facing view of A-zone from left aisle near row 5.



Photo 80. Forward-facing view of A-zone from right aisle near row 6.



Photo 81. Aft-facing view of A-zone from right aisle near row 3.



Photo 82. Forward-facing view of B-zone right-side seats (prior to debris removal).



Photo 83. Forward-facing view of B-zone center seats with ceiling debris



Photo 84. Aft-facing view of B-zone seats from left aisle near row 11 after debris removal.



Photo 85. Aft-facing view of B-zone center seats from right aisle near row 10.



Photo 86. Forward-facing view of B-zone from left aisle near row 28 after debris removal.



Photo 87. Forward-facing view of B-Zone from right aisle after debris removal.



Photo 88. Aft-facing view of C-zone from left aisle near row 29.



Photo 89. Forward-facing view of C-zone from left aisle near row 39.



Photo 90. Forward-facing view of C-zone from door 4L.



Photo 91. Forward-facing view of C-zone from right aisle near row 40.



Photo 92. Aft-facing view of C-zone from left aisle near row 36.



Photo 93. C-zone row of seats aft of the right aisle near row 39.



Photo 94. Forward-facing view of C-zone overhead bins in left aisle near row 38.



Photo 95. Aft-facing view of C-zone from left aisle near door 3L.



Photo 96. Forward-facing view of C-zone from the left aisle near row 40.



Photo 97. C-zone seats 38 ABC.



Photo 98. C-zone seats 37 ABC.



Photo 99. Aft-facing view of C-zone from left aisle near row 30.



Photo 100. C-zone center seats, rows 41-42.



Photo 101. C-zone seat row 42.



Photo 102. Seats 42A and B inside door 4L.



Photo 103. Forward-facing view of the aft of the airplane.



Photo 104. Forward-facing view of the aft of the airplane with debris removed.